



PAGE 10F2





WATER CAUSES SPRING TO BEND AND ROTATOR TO TURN




FIG 3